

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>301</i>	LOCATION <i>1902 H St</i>
DATE <i>1/5/33</i>	PURPOSE <i>Reshingle Roof</i>
ZONE <i>M-1</i>	OWNER <i>G. L. ...</i>
	ARCH'T <i>...</i>
	CONT-R <i>...</i>
	PHONES

VAL. <i>1-9</i>	STORIES	ROOMS	APTS.	SIZE
-----------------	---------	-------	-------	------

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

DATE	CONDITION OF WORK-REMARKS
1/25/33	Re Shingling of Roof of 2-Story Residence
	Work Completed by A. W. Campbell
	COMPLETE AND O. K. INSPECTOR