

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <b>5667</b>	LOCATION <b>(1-STORY FRAMED DWG) 2778-21<sup>ST</sup> ST.</b>
DATE <b>Dec. 13, 1929</b>	PURPOSE <b>Re-Roof Only with Composition Shingles</b>
ZONE <b>2-Family Dist</b>	OWNER <b>MRS MAY DODDY</b>
	ROOMS <b></b>
	APTS. <b></b>
	PHONE <b></b>
	ARCH'T <b></b>
	CONTR <b>DALLMAN SUPPLY CO</b>
	VAL. <b>260<sup>00</sup></b>
	STORIES <b>1</b>
	SIZE <b></b>

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
EX Wall	Joints						Chimneys	Cement Tests
DEC 13 1929	Beams and Girders						Fire Place	
SACRAMENTO BUILDING DIV	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	



DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="329 793 476 837">COMPLETED AND O.K.</p> <p data-bbox="1115 819 1250 840">INSPECTOR</p>

