

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>1168</i>	LOCATION <i>1641 S.</i>
DATE	PURPOSE <i>Service Station</i>
OWNER <i>J. Parkerson</i>	PHONES
ARCH'T <i>J. G. Valentini</i>	
CONTR <i>J. G. Valentini</i>	
STORIES <i>2nd +</i>	ROOMS
	APTS.
	SIZE

ISSUED
MAY 15 1927
SACRAMENTO
BUILDING DIVISION

Steel Tested by	<p><i>OK</i></p> <p><i>OK</i></p> <p><i>OK</i></p> <p><i>OK</i></p> <p><i>OK</i></p>	Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfcd. Conc.		Sprinkler System	
Fire Escapes		Floor Tests	
Stand-pipes			

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="282 1004 462 1052">COMPLETED AND O. K.</p> <p data-bbox="1362 1032 1480 1052">Inspector</p>