

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10,583-</i>	LOCATION <i>2121 - 2 St.</i>
DATE <i>8/6/42</i>	PURPOSE <i>Gen. Repairs dwlg.</i>
ZONE	OWNER <i>John Madsen</i>
	ARCH'T.
	CONT'R. <i>Owner</i>

VAL. <i>45000</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
3/18/43	2 nd Insp. Frame for Remodeling interior of 204 O. K. H. W. Campbell
	COMPLETE AND O. K. INSPECTOR