

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-7093</i>	LOCATION <i>1514-30th St.</i>			
DATE <i>9/30/37</i>	PURPOSE <i>Repairs to fire loss add rooms</i>			
ZONE <i>-</i>	OWNER <i>Mrs. L. H. Raby</i>			
	ARCH'T.			
	CONTR. <i>Elton Blair</i>			
VAL. <i>2200⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
10/6	1 st Jarp Frames on Punter
10/22-30	2 nd Jarp Frame on Punter

COMPLETE
AND O. K.

INSPECTOR