

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
8628 Glenroy Way		2777 - Alvarado St. San Leandro Ca.		1-0	
LEGAL DESCRIPTION					
Lot 845 Glenbrook #8					
TITLE AND NAME		ADDRESS		CITY LIC. NO.	
Besco		Same		383-9315	
GEN. CONTR.		ELEC. CONTR.		PLUMBING BY	
Besco		Same		DATE	
MECH. CONTR.		PLBG. CONTR.		MECHANICAL BY	
				DATE	
ARCH. ENGR.		OWNER		CERTIFICATE OF OCCUPANCY	
Brookvale Inc.		2777 - Alvarado St. San Leandro Ca.		ISSUED BY	
CONST. LOAN LENDER		NO. OF STORIES		DATE	
1		5		10-30-67	
BLDG. WIDTH		TOTAL HEIGHT		TOTAL AREA	
REAR YARDS		SET BACK REQ.		C.S.D.	
SIDE YARDS		USE ZONE		C.I. CASE	
R-1		R-1		1394 Sq. Ft.	
PARK'G REQ.		SPACES		EXISTING BLDG'S SAME LOT	
TREES RMVD.		HOW USED		500 gar.	
NATURE OF WORK:-					
Const. dwelling & gar. Plan 403 LB					

PERMIT NO. S.P. - F-7963		ISSUED BY	
7-18-67		ISSUANCE DATE	
\$ 13,800.00		VALUATION	
R.U.F. FEE		INSPECTION RECORD	
\$		REEL NO. 195	
S.M.I. FEE		FRAME NO. 309	
\$		TO	
PLAN CK. FEE		REEL NO. 221	
\$		FRAME NO. 140	
SEWER INCL. FEE		REEL NO. 180	
\$		FRAME NO. 276	
PERMIT FEE		TO 287	
\$ 49.00		Revision	
TOTAL FEES		REMARKS AND/OR VARIANCES	
\$		Dwelling	
\$		JOB FILE	
\$		MICROFILM RECORD	

0507R285 - Rev