

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H 3283</i>	LOCATION <i>1222 - 70th</i>		
DATE <i>9/13/35</i>	PURPOSE <i>Re-roof dwell comp. etc.</i>		
ZONE	OWNER <i>Mrs Samuel Bellam</i>		
	ARCH'T.		
	CON'T.R. <i>J. Edwin Proffers C 1816-51</i>		
VAL. <i>125⁰⁰</i>	STORIES	ROOMS	APTS. <i>2</i>
			SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="323 868 457 909">COMPLETE AND O. K.</p> <p data-bbox="1164 885 1298 909">INSPECTOR</p>