

*R-233 F-573*

Lot #1104 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$55.00

Glenbrook #10 TYPE BUILDINGS *R-191 F-271-276*

|                      |  |
|----------------------|--|
| PERMIT NO.<br>G-2328 | LOCATION 197 - Mossglen Circle A-1 (52)      |
| DATE<br>Jan-9-69     | PURPOSE Const. dwelling & att. gar. M.P.#604 |
| OWNER F WV, Inc.     | 2777-Alvarado St. San Leandro                |
| ZONE<br>R-1          | ARCH'T /Cal.<br>CONT'R Besco Same            |

|               |              |            |                   |                       |
|---------------|--------------|------------|-------------------|-----------------------|
| VAL. \$15600. | STORIES<br>1 | ROOMS<br>5 | APTS.<br>475-gar. | SIZE<br>1,593 sq. ft. |
|---------------|--------------|------------|-------------------|-----------------------|

| INSP.      | DATE           | BLDG. TYPE        | OCCUPANCY GROUP | PHONE (O) (C) |
|------------|----------------|-------------------|-----------------|---------------|
| FORM       | <i>2-6-69</i>  | <i>Hammers</i>    |                 | 383-9315      |
| JOIST      | <i>2-26-69</i> | <i>Parlato</i>    |                 |               |
| FRAME      | <i>4-2-69</i>  | <i>Parlato</i>    |                 |               |
| SHEET ROCK | <i>4-7-69</i>  | <i>Hammers</i>    |                 |               |
| FINAL      | <i>5-13-69</i> | <i>C. Hammond</i> |                 |               |

| DATE    | SPECIAL CONDITIONS OF WORK — REMARKS |           |
|---------|--------------------------------------|-----------|
| 2-18-19 | OK chb                               | Sammons   |
| 3-5-19  | PT not ready                         | Sammons   |
| 5-13-19 | PT Exhaust duct in                   | kitchen   |
|         | inspect                              | Sammons   |
|         |                                      |           |
|         |                                      |           |
|         |                                      |           |
|         |                                      |           |
|         | COMPLETE<br>AND OK                   | INSPECTOR |

H

9