

K 287 F 105

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

PERMIT NO. G-7926		LOCATION 3457 - 10th Avenue A-1 (27)			
DATE Aug 13-70		PURPOSE Repair pest damage to dwelling			
ZONE R-1		OWNER Elizabeth Conballack Same			
		ARCH'T			
		CONT'R Orchard Supply P.O. Box 956			
VAL. \$1,000.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) 446-7821	
FORM					
JOIST					
FRAME	8-15-70	Trust			
SHEET ROCK					
FINAL	9-4-70	M. Conballack			

1. Inspect for proper installation of all materials and workmanship.  
 2. Inspect for proper installation of all materials and workmanship.  
 3. Inspect for proper installation of all materials and workmanship.  
 4. Inspect for proper installation of all materials and workmanship.  
 5. Inspect for proper installation of all materials and workmanship.  
 6. Inspect for proper installation of all materials and workmanship.  
 7. Inspect for proper installation of all materials and workmanship.  
 8. Inspect for proper installation of all materials and workmanship.  
 9. Inspect for proper installation of all materials and workmanship.  
 10. Inspect for proper installation of all materials and workmanship.

2

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<p data-bbox="302 857 428 909"><b>COMPLETE AND OK</b></p> <p data-bbox="1144 884 1269 909"><b>INSPECTOR</b></p>