

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-1287</i>	LOCATION <i>1215 - 57<sup>th</sup> St.</i>
DATE <i>8/18/38</i>	PURPOSE <i>Erect new dwlg. on</i>
ZONE <i>2-Form</i>	OWNER <i>J.W. Santana</i>
	ARCH'T.
	CONTR. <i>John Fernandez</i>

VAL. <i>3500.00</i>	STORIES	ROOMS	APTS.	SIZE
---------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
8/20-38	152 Insp - Frames at Point
9/27-38	2 <sup>nd</sup> Insp - Frames in Point
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>