

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-35776	LOCATION 3332 53rd Street
DATE 7-21-52	PURPOSE Rebuild front & rear porches of
ZONE	OWNER R. O. Ross exist. dwlg.
	ARCH'T.
	CONTR. Owner

VAL. \$300.00	STORIES	ROOMS	APTS.	SIZE
----------------------	----------------	--------------	--------------	-------------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	COMPLETE AND O. K. INSPECTOR